

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 28

Township: 8 North

Range: 1 West

Corner ID: Per I-19


Monument Description & Remarks: Found old rusty Iron Pipe, 0.3' diameter, at West 1/4 corner of section. Iron pipe was painted orange and marked with old orange and pink flagging. Survey lathe stake at corner read "SW corner, NW 1/4, Section 28." County Surveyor note: new monument needed.

References on file in the County Surveyor's Office: Survey by Ben Bledsoe, R.L.S. No. S0559, recorded in Book 4, Page 488 in the Recorder's Office.

RECOVERY TIE DRAWING

Field Book 98-01 Page No. 36

USGS Clear Creek Quad



A - Iron Pipe, rusted, 0.3' diameter

B - North 26 degrees West, 46.81' from iron pipe
Corner of building foundation

C - North 86 degrees East, 6.11' from iron pipe
MAG nail in 6"x 8" fence corner post (RR tie)

D - South 01 degree West, 12.48' from iron pipe
MAG nail in 23" bifurcated Sugar Maple

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 27th day of January, 1998.

Administered by: Surveyor Review Board

